

2003
CAD 3D Engineering
Final Problem

1. Create a full-scale three-dimensional drawing of the Bearing Support Jig.
2. Create a full-scale three-dimensional drawing of the .5-inch shaft with keyway that goes in the hole with the keyway.
3. Create a full-scale three-dimensional drawing of the key for the keyway to lock the shaft on the jig.
4. Assemble all three parts together in one final presentation drawing.

